

1 / 10

Fig. 1





Fig. 2



2 / 10

Fig. 3





Fig. 4



3 / 10

Fig. 5





Fig. 6



4/10

Fig. 7





Fig. 8



5 / 10

Fig. 9




Fig. 10





Fig. 11



6 / 10

Fig. 12




Fig. 13





Fig. 14



7/10

Fig. 15





Fig. 16



8 / 10

Fig. 17





Fig. 18



10 / 10

Fig. 19A





Fig. 19B



winding, crossing and tinning
the X-winding and the Y-winding

Fig. 19C






Fig. 19E



measuring and
packing blister
pack

Fig. 19D



winding of the Z-winding
and tinning the X-winding and
the Y-winding